

CAP Inspection Log

Property Inspected: Union Pacific Railroad Parcel A – Harbor Island, WA

NW Section 7, Township 24, Range 4 Parcel 767180-0548 - Block G, Lot 1-2; and Parcel 767180-0566-Block G Lot 1, both owned by UPRR.

Date/Time of Inspection: 28 December 2017, 0900-0910

Name of Inspector: Scott Adamek, PE

Weather Conditions: Overcast with light rain, about 42 deg F

Pavement Cap Inspection

General: The UPRR parcel observed is entirely capped and is compliant with EPA requirements (see attached Figure 1 – Site Plan and attached photograph log).

Pavement Cap Damage-Location and Description: No pavement cap damage was observed.


Standing water: Precipitation occurred prior to visit - several areas on the pavement were damp in appearance.

Settlement: No obvious sign of differential settlement of more than 1-inch was observed on the pavement. Minor settlement (less than 0.5 inches) was observed in several limited areas on the property.

Changed Conditions: No changes were noticed from the previous inspection that was performed in 2016.

Notes

The areas inspected (not including the landscaped area) were operated by the Alaska Railroad Corporation at the time of the inspection.



Legend

XXXX Fence

UPRR Boundary

2'-3' High Landscaped Area (Pavement Assumed Beneath)

Concrete Slab or Structure

Asphaltic Concrete Surface (Pavement Compliant with EPA Requirements)

Temporary Structures

Figure 1 - Site Plan

Conditions on 28 December 2017

Start ~ 0900

End ~ 0910

Light rain, overcast
 ~ 42°F

FIELD PHOTOGRAPHY LOG SHEET
2017 UPRR Cap Inspection – Harbor Island (Parcel A)
Seattle, Washington

December 28, 2017

Photograph No. 1

Photographed By:
Scott Adamek

Description: View of pavement with active rail lines on UPRR Parcel A. View is towards the southwest. Office trailer is in view at the top right of the photograph.



December 28, 2017

Photograph No. 2

Photographed By:
Scott Adamek

Description: View of pavement with active rail lines on UPRR Parcel A. View is towards the north-northwest. Rail dock ramp and rail-hauling freighter/ferry is in view at top right of photo.



FIELD PHOTOGRAPHY LOG SHEET
2017 UPRR Cap Inspection – Harbor Island (Parcel A)
Seattle, Washington

December 28, 2017

Photograph No. 3

Photographed By:
Scott Adamek

Description: Photo looking across the western portion of the UPRR Parcel A. View is towards the southwest.

